

ANNEX C: TYPICAL RAILWAY TRAIL CONDITIONS (as of Nov - Dec 2016)

Paved Woodland



1: RT West 5 – North of Scott's Hill Rd junction, Sandys



2: RT West 5 – North of Wingood Way Junction, Sandys

Unpaved Hedgerow



3: RT West 1 – next to Harmony Hall, Paget



4: RT West 1 – next to Harmony Hall, Paget

Grassed Woodland



6: RT West 2 – west of Lighthouse Rd junction, Southampton



7: RT West 4 – south of Tribe Rd #5 / Rockaway Rd, Southampton



8: RT West 4 – south of Rockaway Lane, Southampton

Woodland Rockcut



9: RT East 2 – east of Store Hill



10: RT West 1 – west of Harmony Hall, Paget

Wood Stairway



11: RT West 2 – stairs east of North Southampton Princess Entrance Rd



12: RT West 2 – west of Tribe Rd #7, Warwick



13: RT West 2 – west of Tribe Rd #7, Warwick

Unpaved Coastal



14: RT East 3 – Trail section west of Shelly Bay Beach



15: RT East 3 – west of Francis Patton School, Hamilton Parish

Grassed Coastal



16: RT East 3 – Flatts North Inlet, Hamilton Parish



17: RT East 3 – Old Rd. Spur, Hamilton Parish

Coastal Rockcut



18: RT East 3 – Trail section west of Shelly Bay Beach

Unpaved Woodland



5: RT East 2 – east of Cable Hill